

**Number of fire by location (where the fire started), Nunavik, 2017-2018<sup>1</sup>**

(N and %)

| Location   | 2017 |       | 2018 |       |
|--|------|-------|------|-------|
|  | N    | %     | N    | %     |
| Shack (inside storage buliding)                                    | 10   | 13,9  | 8    | 13,1  |
| Other outside areas  | 10   | 13,9  | 4    | 6,6   |
| Kitchen, kitchen alcove  | 8    | 11,1  | 6    | 9,8   |
| Outside parking area   | 9    | 12,5  | 4    | 6,6   |
| Heating equipment room (boilers, water heater space, boilers room) | 4    | 5,6   | 5    | 8,2   |
| Bedroom  | 2    | 2,8   | 6    | 9,8   |
| Living room, family room, game room                                | 0    | 0,0   | 5    | 8,2   |
| Unknown  | 2    | 2,8   | 3    | 4,9   |
| Outside area for waste and garbage                                 | 3    | 4,2   | 1    | 1,6   |
| Exterior staircase, including ramp and emergency staircase         | 2    | 2,8   | 2    | 3,3   |
| Vestibule, corridor  | 4    | 5,6   | 0    | 0,0   |
| Entrance hall, entrance  | 1    | 1,4   | 2    | 3,3   |
| Closet   | 2    | 2,8   | 0    | 0,0   |
| Maintenance workshop   | 0    | 0,0   | 2    | 3,3   |
| Exterior balcony   | 0    | 0,0   | 2    | 3,3   |
| Road traffic area (street, boulevard, highway)                     | 2    | 2,8   | 0    | 0,0   |
| Laundry room   | 0    | 0,0   | 2    | 3,3   |
| Indoor garage  | 1    | 1,4   | 1    | 1,6   |
| Undetermined site of origin  | 0    | 0,0   | 2    | 3,3   |
| Wall, including concealed wall area                                | 1    | 1,4   | 0    | 0,0   |
| Undetermined structural area                                       | 1    | 1,4   | 0    | 0,0   |
| Traffic areas other than road vehicles (sidewalk, bicycle path)    | 1    | 1,4   | 0    | 0,0   |
| Shower room  | 1    | 1,4   | 0    | 0,0   |
| Other circulation aerea  | 1    | 1,4   | 0    | 0,0   |
| Equipment and supply room  | 1    | 1,4   | 0    | 0,0   |
| Crawl space  | 1    | 1,4   | 0    | 0,0   |
| Transformer room, including wiring room                            | 0    | 0,0   | 1    | 1,6   |
| Chimney, flue pipe, gaz exhaust pipe                               | 0    | 0,0   | 1    | 1,6   |
| Ceiling and floor areas, including service spaces                  | 0    | 0,0   | 1    | 1,6   |
| Two sites of origin  | 0    | 0,0   | 1    | 1,6   |
| Storage area for agricultural products (barn, silo)                | 1    | 1,4   | 0    | 0,0   |
| Court, patio, terrace  | 1    | 1,4   | 0    | 0,0   |
| Exterior wall  | 0    | 0,0   | 1    | 1,6   |
| Dining room (mess, cantine, lunchroom, cafeteria)                  | 0    | 0,0   | 1    | 1,6   |
| Bathroom, shower room  | 1    | 1,4   | 0    | 0,0   |
| Other interior storage area  | 1    | 1,4   | 0    | 0,0   |
| Other residential area   | 1    | 1,4   | 0    | 0,0   |
| Total  | 72   | 100,0 | 61   | 100,0 |

Notes:

<sup>1</sup> Based on all reported fires in Nunavik, subject to revision

Source:

Compiled by Public Safety and Fire Prevention, Kativik Regional Government, from data reported by the Fire Department of each Northern Village of Nunavik